INSTALLATION INSTRUCTIONS — 20W COB Spike Light - SP220009

Important Instructions. Please read first.

- **Please follow instructions carefully. Failure to do so will void the warranty. Please ensure installation complies with local law and applicable standards.**

    1. Only use a GLP power supply unit.

    2. Ensure correct input voltage is connected to the luminaire.

    3. Ensure the power is disconnected before making any connections.

    4. Do not make modification nor alter the luminaire without written approval from GLP.

    5. Ensure to keep luminaire in a clean area free of debris.

INSTALLATION

- **Step 1:** Find the location where the luminaire has to be installed. Install a suitable wiring from the power supply (12VAC) to the luminaire.

- **Step 2:** Mount the spike on the surface using a rubber mallet. Depending on type of surface raise the stake by 5cm above the surface as illustrated.

- **Step 3:** Fix the luminaire on the stake by rotating. Make sure the luminaire input cable is rotating with the luminaire to avoid potential damage to the luminaire input cable as illustrated.

- **Step 4:** Connect the luminaire input cable to the main power supply (12V) cable (Do not cut the main power supply cable, just remove insulation, twist the luminaire input cable around the main cable). Ensure the junction box is installed with in one meter from the luminaire as illustrated.


DO NOT CUT MAIN CABLE

- **Step 5:** Solder the connections, wrap the connection with 3M waterproof tape & electrical tape and keep all the connections inside the junction box and put silicon on the top surface of the junction box and close the junction box with screws as illustrated.

- **Step 6:** Adjust the luminaire angle by thumb nut as illustrated.

⚠️ Make sure the main power is switched off during installation.